



Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 5, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the location of the item which applies.

81 0527

OH #182

OH5-000-001-232

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name FOSECO, INC.
Street 20200 Sheldon Road
City Cleveland State Ohio Zip Code 44142

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site FOSECO, INC.
Street 20200 Sheldon Road
City Brookpark County Cuyahoga State Ohio Zip Code 44142

OH D990778490

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Rae, Robert, Environmental Coordinator
Phone (216) 826-4548

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) To (Year)

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☐ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☒ Unknown
- 11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☒ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

000012 MAY 27 81

MAY 27 1981

US EPA RECORDS CENTER REGION 5



416212

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet

1 x 10⁶ est

2000 landfill

gallons

Total Facility Area

square feet

acres

27

G Known, Suspected or Likely Releases to the Environment:


Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☒ Suspected ☐ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.



I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Paul F. Duvall

Street 20200 Sheldon Road

City Cleveland

State Ohio

Zip Code 44142

Signature

Paul F. Duvall

Date

5/21/81

- ☒ Owner, Present
☐ Owner, Past
☐ Transporter
☒ Operator, Present
☐ Operator, Past
☐ Other



FOSECO, INC.

CORPORATE OFFICES: 20200 SHELDON ROAD • CLEVELAND, OHIO 44142-1380 • 216/826-4548

January 6, 1982

U. S. EPA Region S
Sites Notification
Chicago, IL 60604

Dear Sirs:

Attached is an ammended Form 8900-1, Notification of Hazardous Waste Site, for our Cleveland, Ohio facility. This subsequent notification identifies this facility as a non-hazardous site. This change is a result of soil bores and analyses, conducted since the original notification mailed on May 21, 1981, which verified that the area does not exhibit the characteristic of EP Toxicity.

Should there be any questions arising from this notification, please contact me.

Sincerely,

Robert A. Rae
Environmental Coordinator
Corporate Engineering

jk

Enclosure